


USB Connections

By G8MNY

(Corrected Oct 07)

(from info supplied by DG1VV, F5CMK & GM7HUD)



If still confused which way around the connections are. Measure the earth or +5V to prove which way you are looking at your plug/socket PCB pins etc.

Hub PSU requirements: 5V @ 500mA per port. So a 4 port hub needs a 5V 2A PSU.

Y Don't U sent an interesting bul?

73 de John G8MNY @ GB7CIP